


Index No. P 13

CASS COUNTY LAND CORNER RECORD

T. 139 R. 25 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
11421 Corner common to sections 21, 22



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

	Bearing	Tree	Distance
Species	<u>ROAK</u>	<u>W. BIRCH</u>	
Diameter	<u>10"</u>	<u>8"</u>	
Bearing	<u>S75W</u>	<u>EAST</u>	
Distance	<u>46 LKS</u>	<u>21 LKS</u>	

Original Bearing Trees Found			
Species	Bearing	Tree	Distance
Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1907 By JOHN CUYO  
Location filed COUNTY SURVEY RECORD BOOK "A" P. 342-345  
Monument END 1 OLD GOVT B.T.: 10" R.OAK S75W 30.4'  
SET POST  
BOOK "B" P. 92-93 GEO A RALPH TIES- SEE BOOK "B" P. 92-93

Evidence of Subsequent Corner Restoration

Year of search 1910 By CUYO  
microfilm - Roll 105 BK 48 P. 67  
Found corner

Bearing Trees, Reference Objects

Species	<u>BIRCH</u>	_____	_____
Diameter	<u>10"</u>	_____	_____
Bearing	<u>S30-03E</u>	_____	_____
Distance	<u>27.46'</u>	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_