


Index No. P 17

CASS COUNTY LAND CORNER RECORD

T. 139 R. 25 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 22 Corner common to sections 22-23



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species TAM TAM \_\_\_\_\_  
Diameter 6" 8" \_\_\_\_\_  
Bearing S 85W N 80E \_\_\_\_\_  
Distance 9 LKS 17 LKS. \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1909 By JOHN Curo  
Location filed COUNTY SURVEY RECORD BOOK "A" P 342-345  
Monument END BOTH OLD CORNERS: 6" TAM S 85W 5.9'; 8" TAM N 80E 11.2'

Evidence of Subsequent Corner Restoration

Year of search 1910 By Curo  
Microfilm - Roll 105 BK 48 P. 68  
Found corner.

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

\_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_  
Filed at \_\_\_\_\_

By \_\_\_\_\_  
Date \_\_\_\_\_