


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. R3

CASS COUNTY LAND CORNER RECORD

T. 139 R. 25 M. 574 Coordinates: X _____ Y _____
N1/4 30 Corner common to sections 19, 30



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

| | | | | |
|----------|----------------|----------------|-------|--|
| | | Bearing | Trees | |
| Species | <u>Y. ANE</u> | <u>Y. PINE</u> | | |
| Diameter | <u>7"</u> | <u>10"</u> | | |
| Bearing | <u>N2W</u> | <u>S2W</u> | | |
| Distance | <u>49 LKS.</u> | <u>56 LKS</u> | | |

Original Bearing Trees Found

| | | | |
|----------|-------|-------|-------|
| Species | _____ | _____ | _____ |
| Diameter | _____ | _____ | _____ |
| Bearing | _____ | _____ | _____ |
| Distance | _____ | _____ | _____ |

Subsequent Corner Restoration

Year surveyed 1937 By CCC
Location filed Washburn Lake - BK# 2129
Monument Find 4" Cement Post 3 1/4" - w/B.T.
N. Pine Stamp N3E 7 FT

Evidence of Subsequent Corner Restoration

Year of search 1971 By Co. Hist Dept
CO. # 58
Concrete monument in place
1986 BUCKLER MAP SHOWS IN PLACE

Bearing Trees, Reference Objects

| | | | |
|----------|-------|-------|-------|
| Species | _____ | _____ | _____ |
| Diameter | _____ | _____ | _____ |
| Bearing | _____ | _____ | _____ |
| Distance | _____ | _____ | _____ |

Bearing Trees, Reference Objects

| | | | |
|-------|-------|-------|-------|
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____