

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. R 7

CASS COUNTY LAND CORNER RECORD

T. 139 R. 25 M. 5TH Coordinates: X _____ Y _____
N 1/4 29 Corner common to sections 20, 29



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species Aspen J. Pine _____
Diameter 7" 12" _____
Bearing S 11 E N 45 E _____
Distance 59 LKS 34 LKS. _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1909 By JOHN CUBO
Location filed COUNTY SURVEY RECORD BOOK "A" P 342-345
Monument END OLD GOVT B.T.S: 7" ASPEN S 11 E 38.9', 12" J. PINE N 45 E 22.4' SET 4x4x48" POST
BOOK "B" P 92-93 GEO. A. RALPH TIES - SEE BOOK "B" P 92-93
1909 - also on microfilm - roll 115 BK 95 P. 7-8

Evidence of Subsequent Corner Restoration

Year of search 1937 By CCC
Washburn Lake - BK# 2 - P. 30 at 2654' from
West 4" SQ Post for 14 15 21' South
N. Line 29 IS 80 CH.

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____