


Index No. T 25

CASS COUNTY LAND CORNER RECORD

T. 139 R. 25 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 25 Corner common to sections 25



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863

Original monument Post

Species	Bearing	Trees
<u>Y. Birch</u>	<u>FIR</u>	
Diameter <u>5"</u>	<u>6"</u>	
Bearing <u>S 45 W</u>	<u>N 80 W</u>	
Distance <u>14 LKS</u>	<u>31 LKS</u>	

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

Original Bearing Trees Found

Species	Bearing	Distance
_____	_____	_____
Diameter _____		
Bearing _____		
Distance _____		

Subsequent Corner Restoration

Year surveyed 1937 By CCC

Location filed Washburn Lake - BK# 2 P. 18

Monument Set Approx 1/4 Cor 4/2 CH from N  
1941 - Emily Game Refuge Book - P. 16 - at 2640'  
from South - set app. cor - 4" Poplar

Evidence of Subsequent Corner Restoration

Year of search July 2004 By CCSO

Set 7/9" ODIP, up 0.3'

Bearing Trees, Reference Objects

Species	Bearing	Distance
_____	_____	_____
Diameter _____		
Bearing _____		
Distance _____		

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>R. Oak</u>	<u>R. Oak</u>	<u>R. Oak</u>
<u>11"</u>	<u>11"</u>	<u>8"</u>
<u>N 21° E</u>	<u>S 51° E</u>	<u>S 50° W</u>
<u>15.97'*</u>	<u>37.41'*</u>	<u>20.21'*</u>

\*distance to double head nail

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed \_\_\_\_\_

Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_