Index No. A 13

CASS COUNTY LAND CORNER RECORD

T. 139 R. 26 M. 5TH Coordinates: X _____ Y _____

NE 4 Corner common to sections 3,4 AND 33,34 - 140-26



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863

Original monument POST

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	Y. PINE	Y. PINE	W. PINE	W. BIRCH
Diameter	12"	21"	13"	7"
Bearing	N30W	N34E	S57E	S24W
Distance	35 LKS	56 LKS	60 LKS	66 LKS

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1937 By CCC

Location filed Washburn Lake - BK # 7

Monument Fnd iron pipe - run South

1938 - CCC - 1835' South To Ferhs road

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____