


T. 139 R. 26 M. 5TH Coordinates: X _____ Y _____
N/4 3 Corner common to sections 3 AND 34-140-26



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species Y. PINE ASPEN
Diameter 14" 9"
Bearing N18E S69W
Distance 60 LKS 55 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1938 By CCC
Location filed Washburn Lake - BK# 20, P. 40
Monument Corner 100' west of Fehrs Road

Evidence of Subsequent Corner Restoration

Year of search 1998 By Landecker
Found Corner and set Steel Fence Post adjacent.

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

J. Pine J. Pine J. Pine
9" 16" 12"
N43°E East S75°E
68.63 52.31 51.12
Nail & Cap Nail & Cap Nail & Cap

A-15

Subsequent Corner Restoration

Year surveyed 7/2002 By M. Stefan
Location filed _____
Monument 2" iron pipe on 1/2" Rod along side of fence post and witnessed:
9" J. Pine N43°E 68.63'
16" J. Pine East 52.31'
12" J. Pine S75°E 51.12'
Cert. of location was filed.

Evidence of Subsequent Corner Restoration Found

Year of search July 1930 By J. H. Flynn
Twp rd order shows corner

1998 CCSO

Ed 2" I.P. w/ steel cap, up 0.8' above water, steel post adjacent on W side.

8" J. Pine N58°E 68.83'
14" J. Pine S81°E 52.42'
12" J. Pine S63°E 51.23'

Remonumentation certificate prepared 2/12/05
Filed at CCRO Dec. #A000496588

By M. Stefan #12261
Date 3/29/05