


Index No. E13

CASS COUNTY LAND CORNER RECORD

T. 139 R. 26 M. 5TH Coordinates: X _____ Y _____
NE 9 Corner common to sections 3, 4, 9, 10



O = Corner

EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed 1863
Original monument POST

Year of search _____ By _____
Monument found _____

Species	Bearing Trees			
	<u>W. PINE</u>	<u>BL. OAK</u>	<u>W. PINE</u>	<u>W. PINE</u>
Diameter	<u>30"</u>	<u>8"</u>	<u>24"</u>	<u>16"</u>
Bearing	<u>N15E</u>	<u>S69E</u>	<u>S14W</u>	<u>N38W</u>
Distance	<u>47 LKS</u>	<u>40 LKS</u>	<u>29 LKS</u>	<u>18 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Year surveyed 1937 By CCC
Location filed Wash burn Lake - BK # 7
Monument at 5280' from North - set 4" sq oak
for approx cor. - Found birch stake 40' from NW 1/4
35' S and 5' W of approx cor.

Year of search _____ By _____

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance

Species	Diameter	Bearing	Distance

E-13

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____
Location filed _____
Monument Mar 1989 J. Walker #16098
Cert. of Surv. shows Mon. Found

Year of search _____ By _____

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____