


Index No. E15

CASS COUNTY LAND CORNER RECORD

T. 139 R. 26 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N1/4 10 Corner common to sections 3, 10



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>W. PINE</u>	<u>W. PINE</u>	_____
Diameter	<u>18"</u>	<u>26"</u>	_____
Bearing	<u>N15E</u>	<u>S29E</u>	_____
Distance	<u>69 LKS</u>	<u>33 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1937 By CCC  
Location filed Washburn Lake - BK# 3 P. 62  
Monument Iron pipe South of fence corner

Evidence of Subsequent Corner Restoration

Year of search 4/19/88 By John Walker / DNR  
Set 1 1/4" x 1 1/4" x 20" perforated steel tube  
with aluminum cap.  
Filed corner cert. Doc. # 312282.

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>Birch</u>	<u>OAK clump</u>	<u>DEAD PINE</u>	<u>Twin Birch</u>
<u>15"</u>	<u>6" ± 13"</u>	<u>(6LO BT)</u>	<u>5"</u>
<u>23°</u>	<u>75°</u>	<u>145°</u>	<u>173°</u>
<u>40.89'</u>	<u>42.37'</u>	<u>21.78'</u>	<u>36.81'</u>

E-15

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
5-22-89 Cert. Filed by John Walker, RLS 16098  
Doc. # 312282.

1998 - Landecker & Assoc - Certificate  
of survey indicates DNR survey  
marker found.

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_