


T. 139 R. 26 M. 5TH Coordinates: X _____ Y _____
NE 10 Corner common to sections 2, 3, 10, 11



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing Trees			
	BR. OAK	BL. ASH	W. BIRCH	BR. OAK
Diameter	16"	14"	6"	10"
Bearing	N 85 E	N 71 W	S 45 E	S 80 W
Distance	48 LKS	47 LKS	56 LKS	26 LKS

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed 1937 By CCC
Location filed Washburn Lake BK#1 P33
Monument Find 2" I.P. 82.42 CH from N
BK#3 P. 62 - I.P. 5 CH E. of Hwy
16" Elm w/ tag 15' South
1938 - BK# 20 P. 40 - Hwy #6 366' west and
16 75' North
Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance

Evidence of Subsequent Corner Restoration

Year of search 1954 By DNR - Engineering
Map in notes in file

Found 2" I.P.

2-17-88 John Walker / DNR - Set 2" I.P. with 3" cap on rod in pipe

Bearing Trees, Reference Objects			
W. Oak	W. Oak	Ash	W. Oak
8"	8"	6"	8"
294°	29°	112°	230°
37.96'	33.30'	29.65'	13.13'

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
5-22-89 Cert. Filed by John Walker, PLS 16088
Doc. # 312279.

1989 - Landecker & Assoc - Certificate of survey indicates iron monument found.