

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. E 2-3

CASS COUNTY LAND CORNER RECORD

T. 139 R. 26 M. 5TH Coordinates: X _____ Y _____
MC# 50 Corner common to sections 6, 7



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument lost

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species W. PINE W. PINE _____
Diameter 10" 10" _____
Bearing N 82 E S 40 E _____
Distance 33 LKS 25 LKS. _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1981 By DNK-Engineering
Location filed Map notes in file
Monument End 1 1/2" l.p. up 1.9' 13' Elm 1.77' w
has a rusted yellow tag

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species Birch R. oak Elm Top
Diameter TRIPLE 8-10" 13" 13" Lake Bank
Bearing N 60 E S 10 E West West
Distance 16.36' 15.90' 1.77' 13'

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____