


Index No. E 25

CASS COUNTY LAND CORNER RECORD

T. 139 R. 26 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 1/2 Corner common to sections 1, 12 AND 6, 7 - 139-25



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing	Trees	Distance
<u>Y. PINE</u>	<u>Y. PINE</u>	<u>W. PINE</u>	<u>W. PINE</u>
<u>10"</u>	<u>22"</u>	<u>20"</u>	<u>18"</u>
<u>N 22 E</u>	<u>S 38 E</u>	<u>S 73 W</u>	<u>N 12 W</u>
<u>26 LKS</u>	<u>48 LKS</u>	<u>44 LKS</u>	<u>83 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1920 By BEN CLARK  
Location filed COUNTY BOOK "C" P. 541  
Monument SET CORNER PROPORTIONALLY. SET 2 1/2 x 36"  
CAPPED I.M.

Evidence of Subsequent Corner Restoration

Year of search 1937 By CCC  
Washburn Lake - BK # 4 P. 2  
Started east from Sel. Cor.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>IRONWOOD</u>	<u>6"</u>	<u>N 60-45</u>	<u>37.8'</u>
<u>BASSWOOD</u>	<u>10"</u>	<u>S 55-45</u>	<u>66'</u>
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_