


Index No. E 5-6

CASS COUNTY LAND CORNER RECORD

T. 139 R. 26 M. 5TH Coordinates: X _____ Y _____
MC # 49 Corner common to sections 5, 8



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>W. PINE</u>	<u>W. PINE</u>	
<u>9"</u>	<u>12"</u>	
<u>S.D.W</u>	<u>N.R.O.W</u>	
<u>25 LKS</u>	<u>20 LKS</u>	

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed 1936? By CCC
Location filed Wash burn Lake - BK# 3 P. 42
Monument l.p.

Evidence of Subsequent Corner Restoration

Year of search 1983 By DNR - Engineering
Map notes in file
Find 1 3/4" l.p. up 1.8' 25' w. of waters edge

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____