


Index No. 65

CASS COUNTY LAND CORNER RECORD

T. 139 R. 26 M. 5th Coordinates: X _____ Y _____
E 1/4 Corner common to sections 7, 8



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument POST

Bearing Trees

Species	<u>TAM</u>	<u>TAM</u>
Diameter	<u>3"</u>	<u>4"</u>
Bearing	<u>N80E</u>	<u>S50W</u>
Distance	<u>22 LKS</u>	<u>25 LKS</u>

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Subsequent Corner Restoration

Year surveyed 1936? By CCC
Location filed Washburn Lake - BK#3 P. 39
Monument Found 1.1. ONE-W Drushed line 42CH
S. OF NE T
B.T.S ON P. 41
1940 - BK#4 started S. from 1.1.

Bearing Trees, Reference Objects

Species	<u>SP</u>	<u>Tum</u>
Diameter	<u>5"</u>	<u>8"</u>
Bearing	<u>S32W</u>	<u>N43W</u>
Distance	<u>11 Paces</u>	<u>19 Paces</u>

1936 TIES

Evidence of Subsequent Corner Restoration

Year of search 1938 By CCC
Washburn Lake - BK# 20 P. 51
Corner is 1045' South of Muchow's Road

Bearing Trees, Reference Objects

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Subsequent Corner Restoration

Year surveyed 1983 By DNR-Engineering
Location filed Map notes in file
Monument Found 2 1/2" 1.1. in Swamp up 1.3'

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____