


T. 139 R. 26 M. 5th Coordinates: X _____ Y _____
MC# 43 Corner common to sections 9, 16



o = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

	Bearing Trees	
Species	<u>ASPEN</u>	<u>W. PINE</u>
Diameter	<u>5"</u>	<u>8"</u>
Bearing	<u>S10W</u>	<u>N10E</u>
Distance	<u>21 LKS</u>	<u>32 LKS</u>

Original Bearing Trees Found	
Species	_____
Diameter	_____
Bearing	_____
Distance	_____

Subsequent Corner Restoration

Year surveyed 1937 By CCC
Location filed Washburn Lake - BK# 3 P. 36
Monument End up. MC 139' west of point
in lake on Ch. N. of S1/4 sec 16
1938 - BK# 9 at 3411.2' from E offset 13.8' South
to l.p. MC

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	_____
Diameter	_____
Bearing	_____
Distance	_____

Bearing Trees, Reference Objects

_____	_____
_____	_____
_____	_____
_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - AUDITORS PLAT OF LAKE WASHBURN OUTLOTS
JOHN M. GREENE 1923
PLAT - OUTLOT "A" OF AUDITORS PLAT OF LK. WASHBURN/OUTLOTS
JAMES H. FLYNN 1928
PLAT - SUN ACRES
DEAN ANDERSON 1971 IRONS IN PLACE - NOT LABELED MC

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____