


T. 139 R. 26 M. 5TH Coordinates: X _____ Y _____
N 1/4 15 Corner common to sections 10, 15



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees	Distance
<u>UPINE</u>	<u>14"</u>	<u>W. PINE</u>	<u>15"</u>
<u>14"</u>	<u>N49W</u>	<u>530E</u>	<u>60 LKS</u>
<u>15"</u>	<u>20 LKS.</u>		

Species	Bearing	Trees	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1907 By JOHN CURG
Location filed COUNTY SURVEY RECORD BOOK "A" P 390-398
Monument FIND STUMPS OF BOTH B.T.S. SET CORNER

Evidence of Subsequent Corner Restoration

Year of search 1937 By CCL
Washburn Lake - BK# 3 P. 61
Pick up blazed line 40 ch. E. of Approx Cor.

Bearing Trees, Reference Objects

Species oak
Diameter 3"
Bearing S 11 E
Distance 13.70'

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed 1-28-88 By John Walker / DNR
Location filed Cert. Filed Doc. # 312270
Monument Set 1 1/4" x 1 1/4" x 20" perforated steel tube with aluminum cap up 1/2'. Ties:
GLO stump 311° 39.62'; 8" Red Oak North 2.20';
10" Birch 118° 40.17'; 6" Basswood 245° 7.09';
8" Red Oak 300° 2.90'.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

4/20/04 J.L & E.L. CASS LAND DEPT FOUND
MON IN GOOD CONDITION
10" BIRCH S65°E 40.25 IS DEAD
RESOURCE GRAVE COORDS

UTM 15 0427238 ELEV 1443'
5798201