


Index No. J 5

CASS COUNTY LAND CORNER RECORD

T. 139 R. 26 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 18 Corner common to sections 7, 8, 17, 18



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

	Bearing Trees			
Species	<u>R. OAK</u>	<u>R. OAK</u>	<u>R. OAK</u>	<u>R. OAK</u>
Diameter	<u>8"</u>	<u>8"</u>	<u>8"</u>	<u>10"</u>
Bearing	<u>N65E</u>	<u>N43W</u>	<u>S20E</u>	<u>S62W</u>
Distance	<u>64 LKS.</u>	<u>54 LKS</u>	<u>62 LKS</u>	<u>62 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1936 By CCC  
Location filed Washburn Lake - BK# 3 P. 39  
Monument End iron pipe sec Cox. on E-W  
brushed line  
1940 - BK# 4 at 5282' from N - k. to old line 1.P.  
43' E.

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By W. BUCKLER  
1986 MAP SHOWS IN PLACE

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
PLAT - VINES - A - PLANTY ON LAKE WASHBURN  
J. CALVIN BARKER 1948

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_