Index No. N 9

CASS COUNTY LAND CORNER RECORD

T. 139 R. 26 M. 5TH Coordinates: X _____ Y _____

NE 20 Corner common to sections 16, 17, 20, 21



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863

Original monument POST

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	N. PINE	N. PINE	N. PINE	N. PINE
Diameter	10"	9"	20"	8"
Bearing	N38E	N30W	S56E	S67W
Distance	37 LKS	51 LKS	190 LKS	24 LKS

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1938 By CCC

Location filed Washburn Lake - BK# 6 P.58

Monument Started N. from Approx Cor.

1986 BUCKLER MAP SHOWS INPLACE

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____