


Index No. Q-R 25

CASS COUNTY LAND CORNER RECORD

T. 139 R. 26 M. 574 Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
MC # 5 Corner common to sections 24 and 19-139-25



EXISTING SURVEYS

Original Government Survey  
 Year surveyed 1863  
 Original monument Post

Original Evidence Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Bearing Trees  
 Species TAM CEGAR  
 Diameter 12" 6"  
 Bearing N9E N81W  
 Distance 26 LKS. 16 LKS

Original Bearing Trees Found  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Subsequent Corner Restoration  
 Year surveyed 1937 By CCC  
 Location filed Washburn Lake - BK# 2 P. 7  
 Monument Find 4" concrete post and BIT: 4" cedar  
15 LKS NW of post Find cor. 69 LKS E. of line

Evidence of Subsequent Corner Restoration  
 Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Bearing Trees, Reference Objects  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

Subsequent Corner Restoration  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
PLAT - BANNISTER'S LAKE LEAVITT ADDITION  
ELMORE M. WILSIE 1957

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_