

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. R 21

CASS COUNTY LAND CORNER RECORD

T. 139 R. 26 M. 5th Coordinates: X _____ Y _____
NE 26 Corner common to sections 23, 24, 25, 26



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees	
<u>W. PINE</u>	<u>W. PINE</u>	<u>W. PINE</u>	<u>W. PINE</u>
Diameter <u>5"</u>	<u>7"</u>	<u>8"</u>	<u>8"</u>
Bearing <u>N10E</u>	<u>N70W</u>	<u>S65E</u>	<u>S40W</u>
Distance <u>59 LKS.</u>	<u>30 LKS</u>	<u>6 LKS</u>	<u>34 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1916 By JOHN CURG
Location filed COUNTY SURVEY RECORD BOOK "B" P. 191-194
Monument FIND OLD GOUT B.T STUMPS OF SEENW B.TS.
SET 2x4x8" IRON

Evidence of Subsequent Corner Restoration

Year of search 1936? By CCC
Washburn Lake - BK # 3 P. 64
Conc. Post Sec. cor.

1961 - Co. Hwy Dept. - Co. RD # 58 - Found
Concrete Mon. in place 1778' N of E

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>N. PINE</u>	<u>W. PINE</u>	<u>W. PINE</u>
Diameter <u>14"</u>	<u>15"</u>	<u>14"</u>
Bearing <u>N40-30W</u>	<u>N44-05E</u>	<u>S32-15E</u>
Distance <u>38.40'</u>	<u>100.50'</u>	<u>130.70'</u>

Bearing Trees, Reference Objects

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration R 21

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - ROOSEVELT TRAILS
J.P. LARSON 1927

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____