

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. R 25

CASS COUNTY LAND CORNER RECORD

T. 139 R. 26 M. 5TH Coordinates: X _____ Y _____
NE 25 Corner common to sections 24, 25 AND 19, 30 - 139-25



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing Trees			
	<u>Y. PINE</u>	<u>FIR STUB</u>	<u>Y. PINE</u>	<u>Y. PINE</u>
Diameter	<u>12"</u>	<u>6"</u>	<u>10"</u>	<u>13"</u>
Bearing	<u>N47E</u>	<u>S60E</u>	<u>S28W</u>	<u>N51W</u>
Distance	<u>50 LKS</u>	<u>44 LKS</u>	<u>19 LKS</u>	<u>53 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1937 By CCC
Location filed Washburn Lake - BK# 2 P. 7
Monument Set Approx Cor 78 LKS E. of Random Line
CCC - 1937 - BK# 2 P. 29 End 4" Cement Post ^{29/19} _{25/30}
8" N. Pine N10E 15ft w/ yellow tag

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Evidence of Subsequent Corner Restoration

Year of search 1938 By CCC
Washburn Lake - BK# 20 P. 53
Set control post at corner by side of resort road to Mannings - also control post 11464' south of corner at Switzer Road
1986 BOCKLER MAP SHOWS IN PLACE

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

R-25

Subsequent Corner Restoration

Year surveyed 1971 By Co. Hwy Dept
Location filed Co RD# 5B
Monument Found concrete Monument in place

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - ROOSEVELT TRAILS
J.P. LAESON 1927
May 2003 B. Grinn # 17253
Cert. of Surv. shows Mon. found

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____