


Index No. V 11

CASS COUNTY LAND CORNER RECORD

T. 139 R. 26 M. 5th Coordinates: X _____ Y _____
N 1/4 33 Corner common to sections 28, 33



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>Y. PINE</u>	<u>W. PINE</u>	_____	_____
Diameter	<u>18"</u>	<u>11"</u>	_____	_____
Bearing	<u>S65E</u>	<u>N66W</u>	_____	_____
Distance	<u>54 LKS</u>	<u>82 LKS.</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1916 By John Curo
Location filed COUNTY SURVEY RECORD BOOK B' P. 187-190
Monument SET 4x4x 48" OAK POST PROPORTIONALLY.
SET 2x48" IRON BOILER TUBE

Evidence of Subsequent Corner Restoration

Year of search 1936? By CCC
Washburn Lake - BK#3 P. 32
at 80 CH From N - End Iron pipe

Bearing Trees, Reference Objects

Species	<u>R. OAK</u>	<u>R. OAK</u>	_____	_____
Diameter	<u>7"</u>	<u>4"</u>	_____	_____
Bearing	<u>S8W</u>	<u>N57-30W</u>	_____	_____
Distance	<u>45.20'</u>	<u>53 LKS.</u>	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____