


Index No. V 17-18

CASS COUNTY LAND CORNER RECORD

T. 139 R. 26 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
MC # 30 Corner common to sections 26, 35



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>BL. ASH</u>	<u>W. BIRCH</u>	_____	_____
Diameter	<u>6"</u>	<u>3"</u>	_____	_____
Bearing	<u>N 33 1/2 E</u>	<u>S 80 W</u>	_____	_____
Distance	<u>25 LKS</u>	<u>19 LKS.</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search 7/31/91 By JAMES NIELSEN / MN DOT  
Found 1/2" capped pipe

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Bearing Trees, Reference Objects

<u>Balsam</u>	<u>Twin Ash</u>	<u>Ash</u>	<u>Balsam</u>
<u>10"</u>	<u>10"</u>	<u>12"</u>	<u>10"</u>
<u>N 30 W</u>	<u>WEST</u>	<u>N 15 E</u>	<u>N 50 E</u>
<u>10.74'</u>	<u>4.86'</u>	<u>15.59'</u>	<u>13.13'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
PLAT - LUSCHERS BAY  
OUS HOLMSTROM 1949

6-2-93 Cert. Filed by James Nielsen  
Doc. # 347762

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_