


Index No. V 7

CASS COUNTY LAND CORNER RECORD

T. 139 R. 26 M. 5TH Coordinates: X _____ Y _____
N 1/4 32 Corner common to sections 29, 32



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument POST

	Bearing Trees	
Species	<u>W. BIRCH</u>	<u>W. BIRCH</u>
Diameter	<u>6"</u>	<u>5"</u>
Bearing	<u>N 34 W</u>	<u>S 73 W</u>
Distance	<u>16 LKS</u>	<u>28 LKS</u>

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1916 By JOHN C. CRO
Location filed COUNTY SURVEY RECORD BOOK "B" P. 107-190
Monument SET 4x4x48" N. PINE POST PROPORTIONALLY
SET 2x48" IRON BOILER TUBE

	Bearing Trees, Reference Objects	
Species	<u>N. PINE</u>	_____
Diameter	<u>10"</u>	_____
Bearing	<u>S 62-70 W</u>	_____
Distance	<u>40.60'</u>	_____

Evidence of Subsequent Corner Restoration

Year of search 1937 By CCC
Washburn Lake - BK # 3 P. 34
at 40 CH from E - set stake - old blazed
trees - no scribbling

1986 BUCKLER MAP SHOWS IN PLACE

Bearing Trees, Reference Objects

_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____