Index No. V-W 17

# CASS COUNTY LAND CORNER RECORD

T. 139 R. 26 M. 5TH Coordinates: X _____ Y _____

MC # 14 Corner common to sections 34, 35




## EXISTING SURVEYS

### Original Government Survey

Year surveyed 1863

Original monument M. C. Post

### Original Evidence Found

Year of search _____ By _____

Monument found _____

### Bearing Trees

| | | | | |
|---|---|---|---|---|
| Species | W. BIRCH | SPRUCE | | |
| Diameter | 6" | 5" | | |
| Bearing | N80E | S10W | | |
| Distance | 70 LKS. | 35 LKS. | | |

### Original Bearing Trees Found

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Subsequent Corner Restoration

Year surveyed 1936 ? By CCC

Location filed Washburn Lake - BK#3 P.59

Monument Cor IS 8.47 CH S. of NE 34 (in lake)

### Evidence of Subsequent Corner Restoration

Year of search 7/31/91 By James Nielsen / MN DOT

Found 1½" pipe.

### Bearing Trees, Reference Objects

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Bearing Trees, Reference Objects

| | | | |
|---|---|---|---|
| White Cedar | White Cedar | White Cedar | White Cedar |
| 10" | 10" | 10" | 12" |
| N 75 W | N 4W | N25E | S 60 W |
| 22.25' | 25.35' | 14.95' | 5.70' |

VW 17

### Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

### Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

6-2-93 Cert. Filed James Nielsen

Doc. # 347761.

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____