


Index No. E 17

CASS COUNTY LAND CORNER RECORD

T. 139 R. 27 M. 5TH Coordinates: X _____ Y _____
NE 10 Corner common to sections 2, 3, 10, 11



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1864
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

	Bearing Trees			
Species	<u>TAM</u>	<u>SPRUCE</u>	<u>TAM.</u>	<u>J. PINE</u>
Diameter	<u>8"</u>	<u>7"</u>	<u>10"</u>	<u>8"</u>
Bearing	<u>N18E</u>	<u>N30W</u>	<u>S65E</u>	<u>S41W</u>
Distance	<u>25 LKS</u>	<u>20 LKS</u>	<u>5 LKS</u>	<u>22 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1937 By CCC
Location filed Lake Washburn BK#1 P24
Monument End 2" 1/2" in place 77.76 CH. from South
1936 - BK. 7 P. B. at 77.48 CH. from east. End 1/2" 3.72 CH. S. of Random Line in meadow

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____