


T. 139 R. R7 M. 5TH Coordinates: X _____ Y _____
 M.C.# 3 Corner common to sections 12 AND 7-139-26



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
 Original monument Post

Bearing Trees

Species	<u>W. Pine</u>	<u>Aspen</u>	_____	_____
Diameter	<u>10"</u>	<u>10"</u>	_____	_____
Bearing	<u>S40E</u>	<u>S80W</u>	_____	_____
Distance	<u>110 LKS</u>	<u>31 LKS</u>	_____	_____

Original Evidence Found

Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1937 By CCC
 Location filed Washburn Lake - Bk# 7 P. 37
 Monument at 19.52 CH South of Cor. in lake
set stake for app. M.C.

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____