


Index No. J 25

CASS COUNTY LAND CORNER RECORD

T. 139 R. 27 M. 5TH Coordinates: X Y  
NE 13 Corner common to sections 12, 13 AND 7, 18-139-26



○ = Corner

EXISTING SURVEYS

Original Government Survey			
Year surveyed	<u>1863</u>		
Original monument	<u>Post</u>		
Bearing Trees			
Species	<u>TAM.</u>	<u>TAM.</u>	<u>TAM.</u>
Diameter	<u>7"</u>	<u>5"</u>	<u>4"</u>
Bearing	<u>N 87 1/2 E</u>	<u>N 73 W</u>	<u>S 87 W</u>
Distance	<u>52 LKS</u>	<u>96 LKS</u>	<u>142 LKS</u>

Original Evidence Found	
Year of search	By _____
Monument found	_____
Original Bearing Trees Found	
Species	_____
Diameter	_____
Bearing	_____
Distance	_____

Subsequent Corner Restoration	
Year surveyed	<u>1936 ?</u> By <u>CCC</u>
Location filed	<u>Washburn Lake - BK # 3 P. 31</u>
Monument	<u>Poplar tree blazed on 4 sides yellow</u>
	<u>1937 - BK # 7 P. 37 at 81.25 CH from N. APP.</u>
	<u>cor IS 2.83 CH. W.</u>
Bearing Trees, Reference Objects	
Species	_____
Diameter	_____
Bearing	_____
Distance	_____

Evidence of Subsequent Corner Restoration	
Year of search	By _____
	_____
	_____
	_____
	_____
	_____
Bearing Trees, Reference Objects	
	_____
	_____
	_____
	_____

Subsequent Corner Restoration	
Year surveyed	By _____
Location filed	_____
Monument	_____
	_____
	_____
	_____
	_____
	_____
	_____
	_____
	_____
	_____
	_____
	_____
	_____
	_____

Evidence of Subsequent Corner Restoration Found	
Year of search	By _____
	_____
	_____
	_____
	_____
	_____
	_____
	_____
	_____
	_____
	_____
	_____
	_____
	_____
	_____

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_