


Index No. J5

CASS COUNTY LAND CORNER RECORD

T. 139 R. 27 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 18 Corner common to sections 7, 8, 17, 18



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1864  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing Trees			
	MAPLE	W. PINE	W. PINE	MAPLE
Diameter	10"	10"	16"	8"
Bearing	N25E	N62W	S3E	S15W
Distance	92LKS	17LKS	82LKS	94LKS

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1937 By CCC  
Location filed Washburn Lake - BK#2 P.3  
Monument at 70.81 CH from west 10.33 CH. N  
of 3" SA stake w/ tag

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_