


Index No. N 17

CASS COUNTY LAND CORNER RECORD

T. 139 R. 27 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NERR Corner common to sections 14, 15, 22, 23



EXISTING SURVEYS

Original Government Survey  
Year surveyed 1864  
Original monument lost

Original Evidence Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing		Trees	
	W. PINE	Y. PINE	W. PINE	ASPEN
Diameter	<u>6"</u>	<u>14"</u>	<u>28"</u>	
Bearing	<u>N57E</u>	<u>N55W</u>	<u>S15E</u>	<u>S10W</u>
Distance	<u>42 LKS.</u>	<u>43 LKS.</u>	<u>86 LKS.</u>	<u>83 LKS.</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1937 By TCC  
 Location filed Lake Washburn BK#1 P 22  
 Monument Find 4" sq stake & BIT: N. Pine stump  
N38W 96 LKS 91.92 CH from S  
1936 - BK#7 P. 14 at 80 CH from E - set  
3" oak stake

Evidence of Subsequent Corner Restoration

Year of search 1937 By CCC  
Washburn Lake - BK#1 B  
Find stumps of NE, NW & SE BITS. Set 1 1/2 x  
54" iron pipe w/ 2 1/4" cap 2' above ground  
Tie to Swamp to east checks  
 7/39  
 1938 - BK#20 - set control post at cor. on S side road

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search 7/1999 By CCSO

Found 1.5" ODIP w/plumber cap  
up 2' leaning, but in good  
condition, 16 1/2 S. of E Co. Rd #  
and witness as follows:  
Pine sto S15°E, 56.8' (GLO)  
8" Maple N41°W, 43.64'  
11" B. oak N19°E, 39.28'  
6" Ash S27°E, 23.09'  
B. Oak S32°W, 67.04'

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_