


T. 139 R. 27 M. 5TH Coordinates: X Y
NE 24 Corner common to sections 13, 24 and 18, 19-139-26



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863

Original monument Post

Species	Bearing	Trees	Distance
<u>TAM</u>	<u>SPRUCE</u>	<u>TAM</u>	<u>W. Pine</u>
<u>8"</u>	<u>6"</u>	<u>9"</u>	<u>17"</u>
<u>N18E</u>	<u>S81E</u>	<u>S72 1/2 W</u>	<u>N63W</u>
<u>33 LKS</u>	<u>105 LKS</u>	<u>57 LKS</u>	<u>69 LKS</u>

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

O = Corner

Subsequent Corner Restoration

Year surveyed 1938 By CCC

Location filed Washburn Lake - BK#3 P. 71

Monument l.p. also 4" Tam blazed on 3 sides to W.
1937 - BK# 7 P. 38 at 19.75 CH From N -
End l.p.
1939 - BK#8 started S. from l.p.

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Evidence of Subsequent Corner Restoration

Year of search 1938 By CCC

Washburn lake - BK# 20 Set control post at
Corner on South side of road

1964 - Co Hwy Dept. - CARD#48
2" capped l.p. w/ forestry marker

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed 1984 By W. Buckler

Location filed Copy in CCSSO file #98002

Monument Ed 2" pipe w/oval cap 4' S.
of Gravel Road

18" Tamarack West, 106.3'
3/8" Hole in Cul. NW, 86.0'
4" W. Oak, NE, 35.77'
4" W. Oak, SE, 37.87'
24" Spruce, SE, 37.35'

1999 - CCSSO crew set a 7/8" IP w/cap
#16459 from Oak & Spruce ties. New
witnesses:

5" W. Oak, NS8°E, 88.35 fd nail
6" W. Oak, S52°E, 37.87 fd nail
24" Spruce, S15°E, 37.35 fd nail
8" Balsam, NS°E, 68.67 dbl hd nail

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CORNER GPS CCSSO 9/10/02

CCSSO 9/10/02 Ed. 7/8" ODIP, capped
RLS #16459, 12' ± S. of E. Co Rd. #48