


Index No. N 9

CASS COUNTY LAND CORNER RECORD

T. 139 R. 27 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 20 Corner common to sections 16, 17, 20, 21



EXISTING SURVEYS

Original Government Survey

Year surveyed 1864  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing Trees			
	<u>TAM.</u>	<u>W. B. ELH</u>	<u>TAM.</u>	<u>TAM.</u>
Diameter	<u>4"</u>	<u>5'</u>	<u>6"</u>	<u>4"</u>
Bearing	<u>N52E</u>	<u>N75W</u>	<u>S45E</u>	<u>S5W</u>
Distance	<u>15 LKS</u>	<u>67 LKS</u>	<u>280 LKS</u>	<u>47 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1909 By JOHN CURO  
Location filed COUNTY SURVEY RECORD BOOK 'A' P 330-340  
Monument FND NWC NE OLD GOVT B.T.S SET 4x4x48" Post

Evidence of Subsequent Corner Restoration

Year of search 1937 (April) By CCC  
Washburn Lake BK 1 P 28 Find Line 82.99  
Ch. from S.

MURPHY  
1937- CCC - Lake Washburn Set APP. Coy 80  
Ch. from west BK 1 P 8

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_