


Index No. P 25

CASS COUNTY LAND CORNER RECORD

T. 139 R. 27 M. 5TH Coordinates: X _____ Y _____
E 1/4 24 Corner common to sections 24 AND 19-139-26



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species ASPEN PINE
Diameter 7" 8"
Bearing S13E S89W
Distance 147 LKS 96 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1940 By CCC
Location filed WASADUNA Lake - BK # 8
Monument started from NE 24 - 2640' S falls on
crack - set cor at 2613' from N 1/4 W of line

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

1986 BUCKLER MAP SHOWS IN PLACE

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____