Index No. V 13

CASS COUNTY LAND CORNER RECORD

T. 139 R. 27 M. 5TH Coordinates: X _____ Y _____

NE 33 Corner common to sections 27, 28, 33, 34



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1864

Original monument Post

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	Spruce	Aspen	Fir	Aspen
Diameter	4"	8"	5"	10"
Bearing	N35E	N50W	S42E	S70W
Distance	10 Lks	34 Lks	8 Lks	7 Lks

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1937 By CCC

Location filed Washburn Lake - Bk #2 P.23

Monument Fnd Approx Post 1.70 ch. west

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____