

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. V 25

CASS COUNTY LAND CORNER RECORD

T. 139 R. 27 M. 5TH Coordinates: X _____ Y _____
NE 36 Corner common to sections 25, 36 AND 30, 31-139-26



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

	Bearing Trees			
Species	<u>J. Pine</u>	<u>Y. Pine</u>	<u>SPRUCE</u>	<u>J. Pine</u>
Diameter	<u>12"</u>	<u>20"</u>	<u>7"</u>	<u>9"</u>
Bearing	<u>N74E</u>	<u>S28E</u>	<u>S20W</u>	<u>N45W</u>
Distance	<u>30 LKS</u>	<u>23 LKS</u>	<u>72 LKS</u>	<u>37 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1930? By CCC
Location filed Washburn Lake - BK# 3 P. 35
Monument at Bl CH. from east - Fnd old stake
E. Line Sec 36 = 5445'
1940 - BK# 8 - at 5280' from N - set temp cor.
1936 BK# 20 P. 52 corner in center of road - control
post 18.6' west

Evidence of Subsequent Corner Restoration

Year of search 1950 By Harold Curo
Microfilm - fall 105 - Curo NOTES - BK 29 - P. 7c
Set 2x24 I.P.

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>J. Pine</u>	<u>J. Pine</u>	_____	_____
<u>14"</u>	<u>14"</u>	_____	_____
<u>N57-04E</u>	<u>S59W</u>	_____	_____
<u>13.95'</u>	<u>25'</u>	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____