


T. 139 R. 27 M. 5TH Coordinates: X _____ Y _____
SE 33 Corner common to sections 33, 34



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing Trees			
	W. PINE	W. PINE	T. PINE	W. PINE
Diameter	<u>20"</u>	<u>24"</u>	<u>22"</u>	<u>15"</u>
Bearing	<u>N23E</u>	<u>S65E</u>	<u>S37W</u>	<u>N65W</u>
Distance	<u>15 LKS</u>	<u>37 LKS</u>	<u>34 LKS</u>	<u>35 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1937 By CCC
Location filed Washburn Lake - BK# 2 p. 6
Monument at 72.26 ch. from west 1.64 ch. N. of
3" sq Aspen stake
1939 - CCC - Washburn Lake - BK# 10 p. 16
at 52.80' from E. Set 3" Dry Aspen Approx Cor.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____