Index No. A 19

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5TH Coordinates: X _____ Y _____

N1/4 2 Corner common to sections 2 AND 35 140-28



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863

Original monument POST

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	TAM	TAM		
Diameter	10"	7"		
Bearing	N20W	S43E		
Distance	5 LKS.	13 LKS		

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1920 By BEN CLARK

Location filed COUNTY RESURVEY "E-8"

Monument IRON MONUMENT

1919, BEN CLARK, COUNTY BOOK "C" P317 FND 2 OLD POSTS AND BOTH GOV'T BTS SET 2X48" I.P.

Evidence of Subsequent Corner Restoration

Year of search 1938 By CCC

Washburn Lake - BK#13 P.3

at 2640' from E - Set approx Cor.

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Bearing Trees, Reference Objects

A19

Subsequent Corner Restoration

Year surveyed 4/01 By CCSO

Location filed file # 2001.017

Monument Found 60d spike, down 0.3', 1'± S. of & CR# 47. Witnessed follows:

3" Tamarack S74°E, 78.64'*

5" Tamarack S30°W, 74.20'*

P. Pole N4°W, 46.28'*

*distance to double head nail

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____