


Index No. A 23

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5TH Coordinates: X N¹⁴ W Y 1
Corner common to sections LAND 36-140-28



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863

Original monument POST

Bearing Trees

Species	<u>W. BIRCH</u>	<u>FIR</u>		
Diameter	<u>7"</u>	<u>7"</u>		
Bearing	<u>N19W</u>	<u>S4W</u>		
Distance	<u>13 LKS.</u>	<u>15 LKS.</u>		

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1920 By BEN CLARK

Location filed COUNTY RESURVEY "E-8"

Monument IRON MONUMENT
1919, BEN CLARK COUNTY BOOK "C" P. 316 SET 2 1/2 x 48" I.P.
P. 333 SET 2 x 48" I.P.

Bearing Trees, Reference Objects

Species	<u>ASH</u>	<u>W. OAK</u>		
Diameter	<u>4"</u>	<u>8"</u>		
Bearing	<u>N18E</u>	<u>S31W</u>		
Distance	<u>18.3'</u>	<u>16.1'</u>		

Evidence of Subsequent Corner Restoration

Year of search 1938 By CCC

Washburn Lake BK# 13 P. 1
at 2640' from E - set approx cor 4" oak

Bearing Trees, Reference Objects

_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____