


Index No. A3

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5TH Coordinates: X N114 6 Y 6 AND 31 - 140 - 28
Corner common to sections 6 AND 31 - 140 - 28



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1863
 Original monument POST

Bearing Trees
 Species LINN. W. MAPLE
 Diameter 7" 5"
 Bearing S37E N35W
 Distance 19 LKS 12 LKS

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration

Year surveyed 1919 By BEN CLARK
 Location filed COUNTY BOOK "C" P. 334
 Monument SET 2 1/2 x 3 1/2" IRON PIPE
COUNTY RESURVEY "E-9" 1922 BEN CLARK
1942 - JOHN Curo, BOOK "D" P. 325 FND I.M.

Evidence of Subsequent Corner Restoration

Year of search 1939 By CCC
Washburn Lake - BK # 12 P. 39
at 2640' from E - Set approx 1/4 cor.

Bearing Trees, Reference Objects

Species	<u>POPLAR</u>	<u>POPLAR</u>	<u>POPLAR</u>	<u>POPLAR</u>
Diameter	<u>10"</u>	<u>8"</u>	<u>8"</u>	<u>10"</u>
Bearing	<u>N</u>	<u>S17W</u>	<u>S17W</u>	<u>NORTH</u>
Distance	<u>44'</u>	<u>50.7'</u>	<u>50.7'</u>	<u>44.00'</u>
	<u>1919 TIES</u>		<u>1942 TIES</u>	

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____