


Index No. C 9

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 5 Corner common to sections 4, 5



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1864  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species Y. PINE W. BIRCH  
Diameter 24" 7"  
Bearing S 88° E N 38° W  
Distance 25 LKS 18 LKS.

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1922 By BEN CLARK  
Location filed COUNTY RESURVEY "E-9"  
Monument IRON MONUMENT  
1919, BEN CLARK, COUNTY BOOK "C" P 328 SET 2 1/2 x 48  
IRON PIPE

Evidence of Subsequent Corner Restoration

Year of search 2000 By CCSO  
Find. incl. 2" ODIP up 1.8'; Good cond.  
no evidence of orig. B.T.'s; Referenced w/  
ties as noted below:

Bearing Trees, Reference Objects

Species J. PINE  
Diameter 9"  
Bearing S 45° E  
Distance 93.8'

Bearing Trees, Reference Objects

R. oak Maple Maple  
8" 10" 11"  
N 30° W S 15° W S 86° E  
25.00' 52.20' 79.31'  
(TAG)

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_