


Index No. E 11

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5TH Coordinates: X _____ Y _____
N 1/4 9 Corner common to sections 4, 9



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1864

Original monument POST

Species	Bearing	Trees
<u>ASPEN</u>	<u>ASPEW</u>	
<u>6"</u>	<u>5"</u>	
<u>N35W</u>	<u>510E</u>	
<u>134ks</u>	<u>74ks</u>	

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1922 By BEN CLARK

Location filed COUNTY RESURVEY "E-9"

Monument IRON MONUMENT
1 1/2" x 48" I.P.
SET 2" x 48" I.P.

Evidence of Subsequent Corner Restoration

Year of search 2000 By CCSO

End, incl. 2" ODIP flush w/ grade. Located 1' W of survey mkr. sign.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>W. PINE</u>	<u>14"</u>	<u>S 75 E</u>	<u>74.6'</u>
<u>N. PINE</u>	<u>12"</u>	<u>S 40 W</u>	<u>79'</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>W. Oak</u>	<u>8"</u>	<u>N 85° W</u>	<u>109.50'</u>
<u>R. Oak</u>	<u>6"</u>	<u>S 8° E</u>	<u>43.69'</u>
<u>Birch (old scar)</u>	<u>8"</u>	<u>S 58° E</u>	<u>53.21'</u>
<u>SVY MKR.</u>		<u>EAST</u>	<u>1.0'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search June 1918 By _____

Two rd order shows no survey

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____