

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____


Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

T. 139 R. 28 M. 5TH Coordinates: X _____ Y _____
NE 9 Corner common to sections 3, 4, 9, 10



EXISTING SURVEYS

Original Government Survey

Year surveyed 1864
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

	Bearing	Trees	
Species	<u>ASPEN</u>	<u>ASPEN</u>	<u>ASPEN</u>
Diameter	<u>5"</u>	<u>5"</u>	<u>5"</u>
Bearing	<u>N35E</u>	<u>N17W</u>	<u>S60E</u>
Distance	<u>47 LKS</u>	<u>37 LKS</u>	<u>27 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed JUNE 17, 1911 By JOHN CURO
Location filed COUNTY SURVEY RECORD BOOK "A" P364-368
Monument FIND STAKE SET BY CURO FROM OLD CORNER
B.TS SET 8 X 8 X 36' CONCRETE POST
1922 - COUNTY RESURVEY "E-9" BEN CLARK
1919, BEN CLARK, COUNTY BOOK "C" P.320 FIND CONCRETE POST

Evidence of Subsequent Corner Restoration

Year of search 1938 By CCC
Washburn Lake - BK# 12 P.5
started E. from corner.
1911 - also on microfilm - roll 115 BK73 P35

Bearing Trees, Reference Objects

Species	_____
Diameter	_____
Bearing	_____
Distance	_____

Bearing Trees, Reference Objects

_____	_____
_____	_____
_____	_____
_____	_____

E-13

Subsequent Corner Restoration

Year surveyed 1999 By CCSO
Location filed Cass. Co.
Monument SET 60P spk w/washer 1' W of
1/4 C.R. 56, 5' S. of 1/4 trail to west and
11' N of 1/4 Driveway to East.

Evidence of Subsequent Corner Restoration Found

Year of search June 1918 By _____
Twp rd order shows no survey
Dec. 1918, Twp rd order shows no survey

REF. TIES:

P. Pole N30°E, 72.12' *
6" Maple S86°W, 60.16' *
10" Tw. W. Oak N66°W, 72.35' *
* distance to double head nail

Replace spike with Alum. cap telspcr