


Index No. ERI

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5TH Coordinates: X _____ Y _____
NE 11 Corner common to sections 1, 2, 11, 12



EXISTING SURVEYS

Original Government Survey

Year surveyed 1864
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	CEDAR	CEDAR	CEDAR	CEDAR
Diameter	6"	8"	9"	12"
Bearing	N75E	N16W	S16E	S80W
Distance	21 LKS	30 LKS	18 LKS	22 LKS

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1920 By BEN CLARK
Location filed COUNTY RESURVEY "E-8"
Monument IRON MONUMENT
1919, BEN CLARK, COUNTY BOOK "C" P. 319 FWD 4x48"
CEDAR POST AND GWT B.B. 6" CEDAR N75E 13.0', 8" CEDAR
N16W 14.4', 9" CEDAR S16E 11.8', 12" CEDAR S80E 14.5'
P. 321 Set 3x30" I.P.
Bearing Trees, Reference Objects

Evidence of Subsequent Corner Restoration

Year of search 1938 By CCC
Washburn Lake - BK# 12 P. 2
at 5017' from east - find 1 P. 40' South
may 1914; Top rd order shows no survey

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____