


Index No. E 25

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5TH Coordinates: X NE 12 Corner common to sections 1, 12 AND 6, 7 - 139-27



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863

Original monument POST

Original Evidence Found

Year of search _____ By _____

Monument found _____

	Bearing	Trees	
Species <u>W. PINE</u>	<u>W. CEDAR</u>	<u>W. CEDAR</u>	<u>SPRUCE</u>
Diameter <u>7"</u>	<u>11"</u>	<u>5"</u>	<u>8"</u>
Bearing <u>N 20 E</u>	<u>S 47 E</u>	<u>S 53 W</u>	<u>N 38 W</u>
Distance <u>14 LKS</u>	<u>17 LKS</u>	<u>23 LKS</u>	<u>50 LKS</u>

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed 1920 By BEN CLARK

Location filed COUNTY RESURVEY "E-8"

Monument IRON MONUMENT

1919, BEN CLARK, COUNTY BOOK "C" P 307 SET 4x48" J. PINE

183' EAST OF CENTER OF RAILROAD TRACK

1919, BEN CLARK, BOOK "C" P 314 SET 3x30" I.P.

Evidence of Subsequent Corner Restoration Found

Year of search 1936 By CC

Washburn Lake - BK # 7 P. 12

Find I.P. marked 7x19

1938 - BK # 12 P. 1 start west from corner.

BK # 20 corner 139.7' east of center on old grade

Bearing Trees, Reference Objects

Species <u>W. PINE</u>	<u>W. PINE</u>
Diameter <u>12"</u>	<u>10"</u>
Bearing <u>S 30 W</u>	<u>N 40 E</u>
Distance <u>61.1'</u>	<u>32.2'</u>

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
