Index No. E5

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5TH Coordinates: X _____ Y _____

NE 7 Corner common to sections 5, 6, 7, 8



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1864

Original monument Post

Bearing Trees				
Species	Aspen	Aspen	Aspen	Aspen
Diameter	4"	7"	4"	5"
Bearing	N30E	N42W	S15E	S21W
Distance	20 LKS.	16 LKS	19 LKS	22 LKS

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1922 By BEN CLARK

Location filed COUNTY RESURVEY "E-9"

Monument IRON MONUMENT

1919, BEN CLARK, COUNTY BOOK "C" P331. SET CORNER. P. 333 SET 2½ X 24" I.P.

Bearing Trees, Reference Objects

Species	W. Pine Stump		
Diameter	24"		
Bearing	N35E		
Distance	6/.8'		

Evidence of Subsequent Corner Restoration

Year of search 1938 By CCC

Washburn Lake - BK# 12 P.10 at 5325' from E - Fnd W. Pine Stump B.T.

July 1915; B.F. Clark Surv. report shows survey

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed 5/02 By CCSO

Location filed

Monument Found 2½" OD I.P./w plumbers cap, up 1.2', 8' S of ℄ trail

8" W. Oak N45°E 60.39' to dbl hd nail
4" W. Oak S52°E 32.39' to dbl hd nail
9" Maple S72°W 57.54' to dbl hd nail
6" Maple N2°W 36.18' to dbl hd nail

Evidence of Subsequent Corner Restoration Found

Year of search Dec. 1919 By _____

Twpmd order shows no survey

June 1918, Twpmd order shows no survey

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____