ndex No. <u>G.0-09.0</u> CASS COUNTY LANI	CORNER RECORD		
T. <u>139</u> R. <u>28</u> M. <u>5th</u> Coordinates: X	Υ		
E 1/4 8 Corner common to sections 8, 9			
EVISTING	SSURVEYS		
Original Government Survey	Original Evidence Found		
Year surveyed _1864	Year of search by		
Original monument Post	Monument found		
	● = Corner		
Bearing Trees	Original Bearing Trees Found		
Species Birch Birch	Species		
Diameter 6" 6"	Diameter		
Bearing N 35° E S 20° W	Bearing		
Distance 11 links 10 links	Distance		
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration		
Year surveyed 6/1911 By J.W. Curo, LS 1428, Co Survy.	Year of search <u>9/1919</u> By <u>B.F. Clark, LS 231</u>		
Location filed: Curo Book 73, page 30	Location filed: Survey Record #434, Book C, page 329		
Monument: go to the ¼ post between secs. 8-9 and look for BTs. here. We find nothing.	Monument: Set Iron post 2.5"x 4' at 5227.35', iron post for cor. to Sec. 4-5-8-9. Thence went S. 2613.6' Set iron post, in ground 2' for the ¼ S. bet. S. 8-9. Pos in S. edge hay meadow. No trees near of any size.		
Bearing Trees, Reference Objects	Bearing Trees, Reference Objects		
Species	Species		
Diameter	Diameter		
Bearing	Bearing		
Distance	Distance		
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration Found		
Year surveyed 12/1921 By B.F. Clark, LS 231	Year of search By		
Location filed: Resurvey E-9 Doc. #69799	Location filed:		
Monument: Iron Monument	Monument:		
in Hay Meadow, at 2631.6'.			
9/2005, CCHD/SO and CCLD #2003.007 Searched for ¼ corner at computed location, no evidence of corner was recovered.			
4/2006, J. Kramer, LS 42619 Certificate of Survey, #5255 Indicates an iron monument set at this corner, at lost position.			
12/2018, CCHD/SO #2018.014 Found 7/8" ODIP, RLS 42619, up 0.5', in open marsh. 11" Burr Oak, S 29 E, 145.05' duplex nail, up 1.0', E. side			
Steel Post, East, 1.4' Steel Sign Post, East, 132.18' Steel Sign Post, South, 200.13'			
Certificate of Location of Government Corner filed in Cass County	ByT.L. Freeman, LS 21367		
Recorders Office as DocumentA000647276	Date 1/10/2019		

Figure 139 R. R. M. Sith Coordinates: X EVY 8. Corner common to sections 6, 9  FXISTING SURVEYS  Original Government Survey  Vear surveyed 1564  Vear of search By.  Original monument 1655  Species Bland Packet  Species Distance 165 6  Subsequent Corner Retarction  Subsequent Corner Retarction  Subsequent Corner Retarction  Fidence of Subsequent Corner Retarction  Subsequent Corner Retarction  Fidence Country Result Country Food: 1329 set 7546  Bearing Distance  Species  Distance  Species  Spec	ndex No. 69 CASS COUNTY LA	ND CORNER RECORD	
EXISTING   SURVEYS   Original Government Survey   Original Evidence Found   Year surveyed   Ref			
EXISTING   SURVEYS   Original Government Survey   Original Evidence Found   Year surveyed   Ref	F/V 8 Corpor common to continue R 9	Y	
Vear surveyed   Corner Restoration   Subsequent Corner Restoration Found   Vear of search   By	Corner Common to sections O//		
Year arreyed /SG/ Distance // SZ/ Bearing Trees / Distance // Subsequent Corner Restoration / Species / Sp		NG SURVEYS	- + 8 - + - 0
Bearing Trees   Bearing Trees   Species   Sp		Original Evidence Found	
Species Breit Brei	Year surveyed 1864	Year of searchBy	+
Species Diameter 6"	Original monument <u>Fost</u>	Monument found	
Species Diameter 6"			O = Corner
Bearing	Species Birch Birch	Criginal Bearing Trees Found L.	
Bearing	Diameter 6" 6"	Diamoto-	
Subsequent Corner Restoration  Fidence of Subsequent Corner Restoration Found  Year surveyed  By  Fernonumentation certificate prepared  By  Remonumentation certificate prepared  By	Bearing N355 520W	58	
Subsequent Corner Restoration  Veer surveyed 1922 By Sept Cliff* Location filed County Results E - 9"  Mayunest IRAM Manuserest Hill, Ben Cliff* Bearing Trees, Reference Objects  Bearing Trees, Reference Objects  Bearing Trees, Reference Objects  Bearing Trees, Reference Objects  Subsequent Corner Restoration  Year surveyed By Year of search By  Year of search By  Remonumentation certificate prepared By  Remonumentation certificate prepared By  Remonumentation certificate prepared By		11	
rear surveyed 1922 By Subsequent Corner Restoration  Subsequent Corner Restoration  Subsequent Corner Restoration  Subsequent Corner Restoration  Year surveyed By Subsequent Corner Restoration  Subsequent Corner Restoration  Year surveyed By Subsequent Corner Restoration  Femonumentation certificate prepared By Subsequent Corner Restoration By Subsequent		- O'S'GREE	
Year surveyed By Subsequent Corner Restoration  Subsequent Corner Restoration  Year surveyed By Subsequent Corner Restoration  Year of search By Subsequent Corner Restoration  Year of search By Subsequent Corner Restoration  Year of search By Subsequent Corner Restoration By Subsequent Corner Restoration Found  Year surveyed By Subsequent Corner Restoration By Subsequent Corner Restoration Found  Year of search By Subsequent Corner Restoration By Subsequent Corner Restoration Found  Year of search By Subsequent Corner Restoration By Subsequent Corner Restoration Found  Year surveyed By Subsequent Corner Restoration By Subsequent Corner Restoration Found  Year surveyed By Subsequent Corner Restoration By Subsequent Corner Restoration Found  Year surveyed By Subsequent Corner Restoration By Subsequent Corner Restoration Found  Year surveyed By Subsequent Corner Restoration By Subsequent Corner Restoration Found  Year surveyed By Subsequent Corner Restoration By Subsequent Corner Restoration Found  Year surveyed By Subsequent Corner Restoration By Subsequent Corner Restoration Found  Year surveyed Borner By Subsequent Corner Restoration Found  Year surveyed Borner By Subsequent Corner Restoration By Subsequent Corner Restoration Found  Year surveyed Borner By Subsequent Corner Restoration By Subsequent Corner Restoration Found  Year surveyed Borner By Subsequent Corner Restoration By Subsequent Corner Restoration By Subsequent Corner Restoration By Subsequent By Subsequent Corner Restoration By Subsequent By Subse	Subsequent Corner Restoration	Evidence of Subsequent (	Corner Restoration
Description   Page	rear surveyed 1922 By BEN CLARK		
Bearing Trees, Reference Objects  Species Diameter Bearing Distance  Subsequent Corner Restoration  Year surveyed By Year of search By  Monument  Monument  By  Remonumentation certificate prepared By  Remonumentation certificate prepared  By  Remonumentation certificate prepared  By  Boaring Trees, Reference Objects  Boaring Trees, Reference Ob	Location filed COUNTY KESURUEF E-9"		· · · · · · · · · · · · · · · · · · ·
Bearing Trees, Reference Objects  Species Diameter Bearing Distance  Subsequent Corner Restoration  Year surveyed By Year of search By  Monument  Monument  By  Remonumentation certificate prepared By  Remonumentation certificate prepared  By  Remonumentation certificate prepared  By  Boaring Trees, Reference Objects  Boaring Trees, Reference Ob	Monument IRON MONUMENT		
Subsequent Corner Restoration  Subsequent Corner Restoration  Year surveyed By Year of search By  Location filed  Monument  Monument  By  Remonumentation certificate prepared By	1914, BEN CLARE, COUNTY BOOK (" 1 329 SET ZHU)		
Subsequent Corner Restoration  Subsequent Corner Restoration  Year surveyed By Year of search By  Location filed  Monument  Monument  By  Remonumentation certificate prepared By			
Subsequent Corner Restoration  Subsequent Corner Restoration  Year surveyed By Year of search By  Location filed  Monument  Monument  By  Remonumentation certificate prepared By			
Subsequent Corner Restoration  Subsequent Corner Restoration  Year surveyed By Year of search By  Location filed  Monument  Remonumentation certificate prepared By  Subsequent Corner Restoration Found  Evidence of Subsequent Corner Restoration Found  Year of search By  Year of search By  Subsequent Corner Restoration Found  Femous of Subsequent Found  Femous of Sub		Bearing Trees, Referenc	a Objects
Bearing Distance  Subsequent Corner Restoration  Evidence of Subsequent Corner Restoration Found  Year surveyed By Location filed  Monument  Monument  By	Species		
Subsequent Corner Restoration  Fear surveyed By Year of search By  Monument  Remonumentation certificate prepared By  Subsequent Corner Restoration Found  Fevidence of Subsequent Corner Restoration Found  Year of search By  Year of search By  By  Remonumentation certificate prepared By  By  By	Diameter		
Subsequent Corner Restoration  Year surveyed	Begring		
Year surveyed By Year of search By Location filed	Distance		· · · · · · · · · · · · · · · · · · ·
Location filed  Monument   Remonumentation certificate prepared  By			
Monument  Remonumentation certificate prepared  By		rear or search by	
Remonumentation certificate prepared			
Remonumentation certificate prepared	MONUMENT		
Remonumentation certificate prepared		<b>[</b>	
Remonumentation certificate prepared			
Remonumentation certificate prepared			
Remonumentation certificate prepared		<b>- I</b>	
Remonumentation certificate prepared			
Remonumentation certificate prepared			
	Personamentation certificate prepared	Pu	
	Transportunia in unitari de la		