


Index No. J 11

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5TH Coordinates: X _____ Y _____
N1/4 16 Corner common to sections 9, 16



EXISTING SURVEYS

Original Government Survey

Year surveyed 1864
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species BIRCH ASPEN _____
Diameter 6" 6" _____
Bearing N70W S10W _____
Distance 14 LKS 4 LKS _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1922 By BEN CLARK
Location filed COUNTY RESURVEY "E-9, E-10"
Monument IRON MONUMENT
1919, BEN CLARK, COUNTY BOOK "C" P. 322 SET 2 1/2" x 1 1/2" IR

Evidence of Subsequent Corner Restoration

Year of search 1982 By G. SURVEYOR
CURT SHEPARD SAID IRON WAS TORE OUT BY
MOTOR GRADER - FND IRON LAYING IN DITCH.
1938- CCC - Washburn Lake - bk #13 P19 at 2640'
from E - set APPROX COR.

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search Dec. 1918 By _____
Twp rd order shows no survey

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____