


T. 139 R. 28 M. 5TH Coordinates: X _____ Y _____
N 14 15 Corner common to sections 10, 15



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1864
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>CEDAR</u>	<u>CEDAR</u>	_____	_____
Diameter	<u>8"</u>	<u>8"</u>	_____	_____
Bearing	<u>N50W</u>	<u>S45E</u>	_____	_____
Distance	<u>3 LKS.</u>	<u>6 LKS.</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1922 By BEN CLARK
Location filed COUNTY RESURVEY "E-9, E-10"
Monument IRON MONUMENT
1919, BEN CLARK, COUNTY BOOK "C" P. 324 IRON POST

Evidence of Subsequent Corner Restoration

Year of search 1938 By CCC
Washburn Lake - BK # 13 P. 17
at 2640' from W. Set approx Cor.

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____