


Index No. J 19

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5TH Coordinates: X _____ Y _____
N 1/4 14 Corner common to sections 11, 14



EXISTING SURVEYS

Original Government Survey

Year surveyed 1864
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>TAM</u>	<u>SPRUCE</u>	_____
Diameter	<u>5"</u>	<u>7"</u>	_____
Bearing	<u>S 48 E</u>	<u>N 60 E</u>	_____
Distance	<u>ROCKS</u>	<u>3 ROCKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1920 By BEN CLARK
Location filed COUNTY RESURVEY "E-B, E-10"
Monument IRON MONUMENT
1919, BEN CLARK, COUNTY BOOK "C" P. 324 IRON POST
P. 336 SET 2 1/2 x 48" I.P.

Evidence of Subsequent Corner Restoration

Year of search 1938 By CCC
Washburn Lake - BK # 13 P. 15
at 2640' from E - set approx 1/4 cor.

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____