


Index No. J 23

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5TH Coordinates: X _____ Y _____
N 1/4 13 Corner common to sections 12, 13



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1864
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species W. PINE W. PINE _____
Diameter 7" 8" _____
Bearing S 20 E N 30 W _____
Distance 8 LKS 9 LKS. _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1920 By BEN CLARK
Location filed COUNTY RESURVEY "E-8, E-10"
Monument IRON MONUMENT
1919, BEN CLARK, COUNTY BOOK "C" P. 324 FND I. P.
✓ SET 2 1/2 x 48" I. P. P. 339 FND TEMP. 11/18

Evidence of Subsequent Corner Restoration

Year of search 1938 By CCC
Washburn Lake - BK # 13 8/13
at 2640' from East - Set approx 1/4 cor 2" Birch

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____